



CONNECTOR REPAIR KITS

- [Home](#)
- [FAQ](#)
- [Repair Parts](#)
- [Splicing Procedure](#)
- [Feedback](#)


[Back to Results](#) [Print](#)

INLINE-BODY/CONSOLE/SEAT CENTER


Full Repair Kit: 68137872AA

No terminal repair kits have been identified.

End View



Isometric View



Removal Tools

A specific removal tool has not been identified.

Pin Information

Cav					Function
Circuit	Gauge	Color			
1	N0	0	NA	NO CONNECT	
1	Z909	18	BK	GROUND	
2	N0	0	NA	NO CONNECT	
3	N0	0	NA	NO CONNECT	
4	N0	0	NA	NO CONNECT	
5	N0	0	NA	NO CONNECT	
6	N0	0	NA	NO CONNECT	
7	Z909	14	BK	GROUND	
8	A932	18	RD/LG	FUSED B(+)	
9	E12	20	OR/GY	PANEL LAMPS DRIVER	
9	N0	0	NA	NO CONNECT	
10	F983	18	PK/YL	FUSED IGNITION SWITCH OUTPUT (RUN-ACC)	

Cav Circuit Gauge Color				Function
11	N0	0	NA	NO CONNECT
12	F928	20	PK/YL	FUSED IGNITION (RUN)
12	N0	0	NA	NO CONNECT
13	F986	16	LB/PK	FUSED IGNITION SWITCH OUTPUT (RUN-ACC)



Mopar is a registered trademark of Chrysler Group LLC. © Copyright 2011 Chrysler Group LLC. All Rights Reserved. Chrysler, Jeep, Dodge, Ram, Mopar and the Pentastar logo are registered trademarks of Chrysler Group LLC. FIAT is a registered trademark of Fiat Group Marketing & Corporate Communication SpA, used under license by Chrysler Group, LLC. GEM and design is a registered trademark of Chrysler Group Global Electric Motorcars LLC, a wholly owned subsidiary of Chrysler Group LLC. ©2011 Chrysler Group LLC, All Rights Reserved. v1.5.4 Built:09/14/2020